



TARCUTTA, LADYSMITH AND URANQUINTY **FLOOD STUDIES**

DESIGN FLOOD MODELLING

VOLUME 2 – FIGURES AND APPENDICES

DRAFT REPORT FOR PUBLIC EXHIBITION

NOVEMBER 2014

Job No: DM304

Date: November 2014 File: TLUFS_V2_DFM_002.doc Rev No: 2.0

Principal: SAB

Authors: BWL/SAB

LIST OF FIGURES

1.1	Catchinent Flan
1.2	Tarcutta Drainage Plan
1.3	Ladysmith Drainage Plan
1.4	Uranquinty Drainage Plan
2.1	Extent of Catchment Specific PMP Ellipses
3.1	Design Water Surface Profiles – Tarcutta Creek (2 Sheets)
3.2	Stage and Discharge Hydrographs – Design Flood Events – Tarcutta Creek (2 Sheets)
3.3	Tarcutta TUFLOW Model Results – 5 year ARI
3.4	Tarcutta TUFLOW Model Results – 10 year ARI
3.5	Tarcutta TUFLOW Model Results – 20 year ARI
3.6	Tarcutta TUFLOW Model Results – 50 year ARI
3.7	Tarcutta TUFLOW Model Results – 100 year ARI
3.8	Tarcutta TUFLOW Model Results – 200 year ARI
3.9	Tarcutta TUFLOW Model Results – 500 year ARI
3.10	Tarcutta TUFLOW Model Results – PMF
3.11	Tarcutta Provisional Flood Hazard and Hydraulic Categorisation of Floodplain - 100 year ARI
3.12	Sensitivity of Flood Behaviour at Tarcutta to 20% Increase in Hydraulic Roughness Values – 100 years ARI 18 Hour Storm
3.13	Sensitivity of Flood Behaviour at Tarcutta to a Partial Blockage of Major Hydraulic Structures 100 year ARI 18 Hour Storm
3.14	Sensitivity of Flood Behaviour at Tarcutta to Levee Failure – 100 year ARI
3.15	Sensitivity of Flood Behaviour at Tarcutta to 10% Increase in Rainfall Intensity - 100 year ARI
3.16	Sensitivity of Flood Behaviour at Tarcutta to 30% Increase in Rainfall Intensity - 100 year ARI
3.17	Impact of Increased Rainfall Intensities on Extent of Flooding at Tarcutta - 100 year ARI
3.18	Interim Flood Planning Area at Tarcutta – Main Stream Flooding Only
4.1	Design Water Surface Profiles – Kyeamba Creek
4.2	Stage and Discharge Hydrographs – Design Flood Events – Kyeamba Creek (2 Sheets)
4.3	Ladysmith TUFLOW Model Results – 5 year ARI
4.4	Ladysmith TUFLOW Model Results – 10 year ARI
4.5	Ladysmith TUFLOW Model Results – 20 year ARI
4.6	Ladysmith TUFLOW Model Results – 50 year ARI
4.7	Ladysmith TUFLOW Model Results – 100 year ARI
4.8	Ladysmith TUFLOW Model Results – 200 year ARI
4.9	Ladysmith TUFLOW Model Results – 500 year ARI
4.10	Ladysmith TUFLOW Model Results – PMF
4.11	Ladysmith Provisional Flood Hazard and Hydraulic Categorisation of Floodplain - 100 year ARI

Sensitivity of Flood Behaviour at Ladysmith to 20% Increase in Hydraulic Roughness Values -100 year ARI 6 Hour Storm 4.13 Sensitivity of Flood Behaviour at Ladysmith to a Partial Blockage of Major Hydraulic Structures -100 year ARI 6 Hour Storm Sensitivity of Flood Behaviour at Ladysmith to 10% Increase in Rainfall Intensity - 100 year ARI 4.15 Sensitivity of Flood Behaviour at Ladysmith to 30% Increase in Rainfall Intensity - 100 year ARI Impact of Increased Rainfall Intensities on Extent of Flooding at Ladysmith - 100 year ARI Interim Flood Planning Area at Ladysmith – Main Stream Flooding Only Design Water Surface Profiles - Sandy Creek 5.1 Stage and Discharge Hydrographs – Design Flood Events – Sandy Creek (2 Sheets) 5.2 Uranguinty TUFLOW Model Results - 5 year ARI 5.3 5.4 Uranquinty TUFLOW Model Results - 10 year ARI 5.5 Uranguinty TUFLOW Model Results - 20 year ARI 5.6 Uranquinty TUFLOW Model Results - 50 year ARI Uranquinty TUFLOW Model Results - 100 year ARI 5.7 Uranquinty TUFLOW Model Results - 200 year ARI 5.8 5.9 Uranquinty TUFLOW Model Results – 500 year ARI Uranguinty TUFLOW Model Results - PMF 5.10 Uranguinty Provisional Flood Hazard and Hydraulic Categorisation of Floodplain - 100 year ARI Sensitivity of Flood Behaviour at Uranquinty to 20% Increase in Hydraulic Roughness Values - 100 year ARI 6 hour storm Sensitivity of Flood Behaviour at Uranquinty to a Partial Blockage of Major Hydraulic Structures – 100 year ARI (2 Sheets) Sensitivity of Flood Behaviour at Uranquinty to Levee Failure – 100 year ARI Sensitivity of Flood Behaviour at Uranquinty to 10% Increase in Rainfall Intensity - 100 year ARI Sensitivity of Flood Behaviour at Uranquinty to 30% Increase in Rainfall Intensity - 100 year ARI 5.17 Impact of Increased Rainfall Intensities on Extent of Flooding at Uranquinty - 100 year ARI

Interim Flood Planning Area at Uranquinty – Main Stream Flooding Only

Catchment Plan









