



FIGURE 8
Calibration event - 1974 - Stage / Discharge Rating Comparison at Hampden Bridge
Gauged vs Modelled

FIGURE 9
Calibration results - 1974 - Hydrograph Comparison



Disclaimer

Inundation patterns and/or peak flood levels shown for design events are based on best available estimates of Murrumbidgee River flood behaviour. Inundation from local overland flow and tributary flow due to local rainfall is not shown and during events actual inundation patterns may vary.



— 1% AEP Flood Contour

Depth (m)

0 - 0.25
0.25 - 0.5
0.5 - 0.75
0.75 - 1
> 1

