ANNEX A: PHOTOS USED FOR VERIFICATON



Photo 1: Open chanel from Bunnings to Sturt Hwy



Photo 4: Edward St/ Morrong St intersection (2)



Photo 2: Pearson St in foreground



Photo 5: Edward St/ Morrong St intersection (3)



Photo 3: Edward St/ Morrong St intersection (1)



Photo 6: Edward St/ Morrong St intersection (4)



Photo 7: Vestey St (1)



Photo 8: Inundation on Vestey St connecting to Moorong St/ Olympic Hwy



Photo 10: Evans St/ Vesty St/ Moorong St looking south



Photo 11: Moorong St/ Flowerdale Rd intersection looing south



Photo 9: Moorong St/ Flowerdale Rd intersection



Photo 12: Moorong St between Flowerdale Rd and Kincaid St



Photo 13: Moorong St/ Kincaid St intersection (1)



Photo 16: Moorong St/ Kincaid St intersection (4)



Photo 14: Moorong St/ Kincaid St intersection (2)



Photo 17: Vestey St (2)



Photo 15: Moorong St/ Kincaid St intersection (3)



Photo 18: Evans St



Photo 19: Evans St



Photo 22: Inundation behind Moorong St



Photo 20: Edward St/ Morrong St intersection (5)



Photo 23: Cnr of Spring St and West Pde



Photo 21: Spring St (1)



Photo 24: Spring St (2)



Photo 25 Inundation on Shaw St (Gurwood St is the horizontal road).



Photo 26: Wollundry Lagoon at Esplanade/ Best St intersection



Photo 27: Wollundry Lagoon and Trail St crossing.



Photo 28: Wollundry Lagoon at Civic precinct (1)



Photo 29: Tarcutta St/ Cross St intersection

Wagga Wagga MOFFS Verification



Photo 30

: Wollundry Lagoon at Civic precinct (2)



Photo 33: Kooringal Rd/ Forge St intersection



Photo 31: Wollundry Lagoon at Civic precinct (3)





Photo 32: Murrumbidgee River at railway bridge



Photo 36: Jones St and Nagle St



Photo 39: Nagle St elbow



Photo 37: Jones St, Nagle St and Copland St looking south



Photo 40: Road at foreground is East West alignment of Nagle Rd.



Photo 38: Nagle St/ Jones St intersection



Photo 41: Sutton St/ Nagle St intersection



Photo 42: Nagle St east end



Photo 45: Railway underpass on Tarcutta St



Photo 43: Nagle St looking west



Photo 46: Bolton Park



Photo 44: Sturt Hwy/ Hammond Av looking west



Photo 47: Bolton Park and Tarcutta St underpass



Photo 48: Bolton Park to the left and low points on Tarcutta St and Sturt Hwy under Railway.



Photo 49: Sturt Hwy between Marshalls Ck and Kooringal Rd.



Photo 51: Sturt Hwy east of Kooringal Rd



Photo 52: Confluence of Marshalls Cka and Gregadoo Ck.



Photo 50: Sturt Hwy between Marshalls Ck and Kooringal Rd.



Photo 53: Open chanel south of Copland St



Photo 54: Inundation behind railway embankment (between Marshalls Ck and Kooringal Rd,



Photo 57: Crooked Ck/ Sycamore Drain upstream of Vincent Rd.



Photo 55: Gregadoo Ck floodway at northern end of Mitchell Rd



Photo 58: Country Golf Club at Lake Albert



Photo 56: Gregadoo Ck at Bakers Ln



Photo 59: Stringybark Ck diversion into Lake Albert.



Photo 60: Plumpton Rd/ Nelson Rd/ Springvale Dr intersection



Photo 61: Springvale Dr (1)



Photo 63: Springvale Dr (3)



Photo 64: Lloyd Rd (1)



Photo 62: Springvale Dr (2)



Photo 65: Lloyd Rd (2)



Photo 66: Farm dam 690m south of Lloyd Rd culvert



Photo 69: Lake Albert



Photo 67: Springvale Dr looking north



Photo 70: Redwood Dr looking north



Photo 68: Plumpton Rd



Photo 71: Gregadoo Ck, airport in background



Photo 72: Gregadoo Ck (1)



Photo 73: Gregadoo Ck (2)



Photo 74: Gregadoo Ck (3)



Photo 75: Brunskills Rd/ O'Heirs Rd looking towards airport




Photo 76: Hampton Bridge gauge